



In order to prepare for your dry run, please review the items and camera angles below. We ask that there be no more than (2) testers to (1) camera for the examination to ensure we can see each technician and laptop clearly. Please mark your camera angles with blue tape prior to your dry run appointment. If you are unable to effectively complete a dry run, any items that were not successfully checked will be your responsibility to take care of prior to your virtual class date.

CONNECTION (DOWNLOAD ZOOM APPLICATION)
Video Audio Constant connection
SETUP
Clean testing space with minimum interruptions Tripod/cell phone mount placement Computer/laptop and equipment placement
EQUIPMENT
Blue masking tape (set 4' from wall and 8' across) Non-Nuclear Gauge or Nuclear Gauge Tape measure Thermal Imaging Gun (specs Tex-244-F) Measuring wheel
2 ft. stick

CAMERA ANGLES







